

Minutes of 6th Inter-Ministerial Committee meeting dated 28.3.2016 for recognition as
Pre-Shipment Inspection Agency

6th meeting of the Inter-Ministerial Committee (IMC) was held on 28.3.2016 at 11:00 a.m. in Room No. 11, H-Wing, Udyog Bhawan, New Delhi under the chairmanship of Shri K.C. Rout, Addl. Director General of Foreign Trade to consider the applications for recognition as Pre-Shipment Inspection Agency (PSIA).

2. The following members attended the meeting:

- (i) Shri Ajeet Singh, Scientific Officer - C, Atomic Energy Regulatory Board
- (ii) Shri S.K. Bhatnagar, Deputy Industrial Adviser, Min. of Steel
- (iii) Shri Arunoday Goswami Jt. DG, DGFT
- (iv) Shri Rajesh Malhotra, Dy. DG, DGFT
- (v) Shri Nirmal Das, FTDO, DGFT

3. The Chairman welcomed the members of the Committee. The representatives of DIPP and MoEF&CC did not attend the meeting.

4. As a follow-up to the 4th IMC meeting held on 22.1.2016, replies were received from 22 applicants. The Committee examined the information provided by the applicants. The Committee was not satisfied by the information given by the applicants regarding date of calibration and date of purchase of survey-meter and spectrometer, and decided that supporting documents may be sought from the applicants (as stated in the Annexure) before the case is considered in the next meeting. The Committee observed that as per Para 2.54 and 2.55 of Handbook of Procedure, 2015-20 read with ANF-2L, an applicant should have at-least one survey-meter and one spectrometer which meet the requirement of AERB to be considered for recognition as PSIA. The details of the radioactivity detection instruments are placed in the Annexure with remarks. The Committee after due deliberations, recommended the following applicants to be considered as PSIA by the competent authority:

Sl. No. 1	Global Mines and Minerals FZE, UAE
Address of Head Office	328, Business Centre-06, Al Mareed Building, RAS AL Khaimah, UAE
Areas applied for	North America, South America, United Kingdom, European Union, Israel, UAE, Bahrain, Kuwait, Oman, Saudi Arabia, Mauritius, Reunion, Thailand, Singapore, South Africa, New Zealand, Australia, South Korea, Bangladesh, Malaysia, Japan.
Explosive Detector	Make-Morphix Technologies, Model-Tracex, Unique No. LOT No. 7 Jun 2016
Decision of the Committee	The Committee noted that the applicant has 30 survey-meters and 9 spectrometers which were found to be acceptable as indicated in Annexure. The applicant has membership of MRAI and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s Global Mines and Minerals FZE, UAE for recognition as PSIA for the areas which they have applied for.

Sl. No. 2	Supreme International FZC, UAE
Address of Head Office	C1-1004, Ajman Free Zone, P.O. Box 2807, Ajman (UAE)
Areas applied for	USA, European Union, Canada, Brazil, Chile
Explosive Detector	Make-7 Solutions-Multi Gas Clip with Pump, Model-MGC-IR-PUMP, Unique No. P4SE290171
Decision of the Committee	The Committee noted that the applicant has 1 survey-meter and 1 spectrometer which were found to be acceptable as indicated in Annexure. The applicant has membership of MRIA and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s Supreme International FZC, UAE for recognition as PSIA for the areas which they have applied for.

Sl. No. 3	Olivine Commercial PTE Ltd., Singapore
Address of Head Office	51 Ayer Rajah Crescent #01-01, Singapore-139948
Areas applied for	Singapore, Indonesia, Bangladesh, China, Thailand, Philippines, Hong Kong, West Africa, North Africa
Explosive Detector	Make-Morphix Technologies, Model-Tracex Explosive Detection Kits-7 Nos., Part No. 510100
Decision of the Committee	The Committee noted that the applicant has 7 survey-meters and 8 spectrometers which were found to be acceptable as indicated in Annexure. The applicant has membership of MRIA and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s Olivine Commercial PTE Ltd., Singapore for recognition as PSIA for the areas which they have applied for.

Sl. No. 4	Tubby Impex P Ltd., New Delhi
Address of Head Office	C-54, 3 rd Floor, South Extension-Part-2, New Delhi-110048
Areas applied for	Russia, South America, Brazil, Namibia, Nepal, Bangladesh, Sri Lanka, United Kingdom, European Union, North America, South Africa, West Africa, Mauritius, Re-Union, South Korea, Indonesia, Singapore, Israel, Australia, New Zealand, Japan, Hong Kong, Malaysia, Saudi Arabia, Bahrain, Kuwait, Oman, Qatar, UAE
Explosive Detector	Make-Morphix Technologies, Model-Tracex Explosive Detection Kits-25 Nos., Part No. 510100-05
Decision of the Committee	The Committee noted that the applicant has 1 survey-meter and 10 spectrometers which were found to be acceptable as indicated in Annexure. The applicant has membership of MRIA and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s Tubby Impex P Ltd., New Delhi for recognition as PSIA for the areas which they have applied for.

Sf. No. 5	Geo-Chem Inspection SDN BHD, Malaysia
Address of Head Office	49A, Jalan Serangkai, 4 Taman bukit Dahlia, 81700 PASIR, Gudang Johar, Malaysia
Areas applied for	Malaysia, Singapore, Indonesia, Bangladesh, Thailand
Explosive Detector	Make-Morphix Technologies, Model-Tracex Explosive Detection Kits-25 Nos.
Decision of the Committee	The Committee noted that the applicant has 2 survey-meters and 1 spectrometer which were found to be acceptable as indicated in Annexure. The applicant has membership of MRAI and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s Geo-Chem Inspection SDN BHD, Malaysia for recognition as PSIA for the areas which they have applied for.

Sl. No. 6	TSK Engineers P Ltd., Chennai
Address of Head Office	No. 12, V.G.P. Layout, Palavakkam, Chennai - 600041
Areas applied for	USA
Explosive Detector	Make-Implant Science, Model QS-H150, Unique No. 0611-A3D-1063
Decision of the Committee	The Committee noted that the applicant has 1 survey-meter and 1 spectrometer which were found to be acceptable as indicated in Annexure. The applicant has membership of MRAI and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s TSK Engineers P Ltd., Chennai for recognition as PSIA for the areas which they have applied for.

Sl. No. 7	Sunshine International Cargo Inspection Services Inc., Philippines
Address of Head Office	Filsyn Compound Brgy. Bon Jose, STA Rosa City, Laguna, 4026, Philippines
Areas applied for	Philippines, Malaysia, Singapore, UAE , USA
Explosive Detector	Tracex Explosive Kits Lot No. 6375, 5 Boxes containing 5 unit each, Part No. 510100
Decision of the Committee	The Committee noted that the applicant has 4 survey-meters and 4 spectrometers which were found to be acceptable as indicated in Annexure. The applicant has membership of MRAI and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s Sunshine International Cargo Inspection Services Inc., Philippines for recognition as PSIA for the areas which they have applied for.

Sl. No. 8	WISE Services FZE, UAE
Address of Head Office	Q1-06012/B, PO Box 124432, Sarjah, Saif Zone, UAE
Areas applied for	Australia, New Zealand, Thailand, Saudi Arabia, Jordan, Middle East (Kuwait, Bahrain, Oman, Qatar, UAE), West Africa, North Africa, European Union, United Kingdom, North America, South Africa, South America, South Korea, Japan, Turkey.
Explosive Detector	Make-Morphix Technologies, Model-Tracex Explosive Detection Kits-25 Nos.
Decision of the Committee	The Committee noted that the applicant has 25 survey-meters and 14 spectrometers which were found to be acceptable as indicated in Annexure. The applicant has membership of MRAI and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s WISE Services FZE, UAE for recognition as PSIA for the areas which they have applied for.

Sl. No. 9	Exim World Ltd., Canada
Address of Head Office	149, George Robinson Drive, Brampton, Ontario, Canada
Areas applied for	Canada, Australia, Hong Kong, Singapore, European Union, North America, Philippines, Thailand, Vietnam, Sri Lanka, Kuwait, Georgia, Libya, Latvia & Lithuania, UAE, West Africa, Bangladesh & Nepal.
Explosive Detector	Make-Morphix Technologies, Model-Tracex Explosive Detection Kits-25 Nos.
Decision of the Committee	The Committee noted that the applicant has 20 survey-meters and 22 spectrometers which were found to be acceptable as indicated in Annexure. The applicant has membership of MRAI and has given declaration about qualification of manpower. The applicant has also given undertaking that they will not issue PSIC to any importer in India which has proprietor/any partner/any Director common with their firm/company. The committee decided to recommend M/s Exim World Ltd., Canada for recognition as PSIA for the areas which they have applied for.

5. The details of deficiencies in the applications of the remaining 13 applicants are listed in the Annexure. The applicants are advised to go through the remarks against their name for complying with the deficiencies appropriately. The next meeting of the Inter-Ministerial Committee will tentatively be held during the last week of April, 2016.

6. The meeting ended with a vote of thanks to the Chair.


 Deputy Director General of Foreign Trade
 Directorate General of Foreign Trade
 Ministry of Commerce
 Government of India
 New Delhi



ANNEXURE TO MINUTES OF 6TH IMC DATED 28.3.2016

Sl. No.	Case No.	Applicant	Make	Model	Sl. No.	Date of calibration	Supporting documents of calibration attached	Date of purchase	Copy of invoice attached	Photographs attached	Remarks
1	3	Global Mines and Minerals FZE, UAE	Atomex	AT6130	20004	04.03.2015	YES	19.03.2013	YES	YES	OK
			Atomex	AT6130	18895	04.03.2014	YES	21.05.2014	YES	YES	OK
			Atomex	AT6130	20107	04.03.2014	YES	21.05.2014	YES	YES	OK
			Atomex	AT6130	20110	04.03.2014	YES	21.05.2014	YES	YES	OK
			Atomex	AT6130	20113	04.03.2013	YES	21.05.2014	YES	YES	OK
			Atomex	AT6130	20809	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20810	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20811	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20812	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20813	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20815	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20817	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20818	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20819	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20820	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20821	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20822	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20823	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20825	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20826	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20827	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20828	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20829	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20830	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20831	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20832	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20833	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20834	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20835	20.07.2015	YES	29.07.2015	YES	YES	OK
			Atomex	AT6130	20836	20.07.2015	YES	29.07.2015	YES	YES	OK
			ATOMTEX	AT1321	040	11.04.2014	YES	21.05.2014	YES	YES	OK
			ATOMTEX	AT1321	041	11.04.2014	YES	21.05.2014	YES	YES	OK
			ATOMTEX	AT1321	042	11.04.2014	YES	21.05.2014	YES	YES	OK
			ATOMTEX	AT1321	043	11.04.2014	YES	21.05.2014	YES	YES	OK
			ATOMTEX	AT1321	081	18.07.2015	YES	29.07.2015	YES	YES	OK
			ATOMTEX	AT1321	083	18.07.2015	YES	29.07.2015	YES	YES	OK
			ATOMTEX	AT1321	084	18.07.2015	YES	29.07.2015	YES	YES	OK
			ATOMTEX	AT1321	087	18.07.2015	YES	29.07.2015	YES	YES	OK
			ATOMTEX	AT1321	088	18.07.2015	YES	29.07.2015	YES	YES	OK
2	7	Afro Asia Inspection SARLU, Togo	RADCOMM	MSPEC	200109	04.06.2015	YES	01.6.2015	YES	YES	OK
			RADCOMM	MSPEC	200110	04.06.2015	YES	01.6.2015	YES	YES	OK
			Radcomm Systems	RHANDY	100300	30.04.2015	Not given	11.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm Systems	RHANDY	100355	12.06.2015	Not given	11.06.2015	YES	YES	Supporting document of calibration not given

3	18	Cayley Aerospace Inc, USA	Thermofisher	FH-40G	30223	06.02.2015	YES	13.04.2015	YES	YES	OK
			Thermofisher	FH-40G	26183	15.06.2014	Not given	23.03.2010	YES	YES	Supporting document of calibration not given
			Radcomm	Syclone	50023	15.04.2015	YES	23.03.2010	YES	YES	Self-calibrated certificate not accepted.
4	21	Sandeep Garg & Company, Gurgaon	Atomtex	AT6130	18861	20.12.2014	YES	28.01.2013	YES	YES	Calibration date has expired
			Atomtex	AT6130	19955	10.09.2014	YES	28.01.2013	YES	YES	Calibration date has expired
			Atomtex	AT6130	19957	10.09.2014	YES	28.01.2013	YES	YES	Calibration date has expired
			Atomtex	AT6130	19959	10.09.2014	YES	28.01.2013	YES	YES	Calibration date has expired
			Atomtex	AT6130	19980	04.05.2015	YES	28.01.2013	YES	YES	OK
			Atomtex	AT6130	20446	18.6.2015	YES	13.07.2015	YES	YES	OK
			Atomtex	AT6130	20448	18.6.2015	YES	13.07.2015	YES	YES	OK
			Atomtex	AT6130	20449	18.6.2015	YES	13.07.2015	YES	YES	OK
			Atomtex	AT6130	20562	18.6.2015	YES	13.07.2015	YES	YES	OK
			Atomtex	AT6130	20564	18.6.2015	YES	13.07.2015	YES	YES	OK
			Atomtex	AT6130	20566	18.6.2015	YES	13.07.2015	YES	YES	OK
			Atomtex	AT6130	20451	18.6.2015	YES	17.07.2015	YES	YES	OK
			Atomtex	AT6130	20455	18.6.2015	YES	17.07.2015	YES	YES	OK
			FLIR	Identifinder	903558-68	08.09.2012	YES	16.01.2013	YES	YES	Calibration date has expired
			FLIR	Identifinder	903558-124	29.08.2012	YES	21.09.2012	YES	YES	Calibration date has expired
			FLIR	Identifinder	903558-126	29.08.2012	YES	09.11.2012	YES	YES	Calibration date has expired
			FLIR	Identifinder	903558-127	29.08.2012	YES	04.10.2012	YES	YES	Calibration date has expired
			FLIR	Identifinder	903555-135	02.09.2012	YES	24.09.2012	YES	YES	Calibration date has expired
			FLIR	Identifinder	903555-136	02.09.2012	YES	24.09.2012	YES	YES	Calibration date has expired
			FLIR	Identifinder	903555-144	26.09.2012	YES	18.01.2013	YES	YES	Calibration date has expired
			FLIR	Identifinder	903555-145	26.09.2012	YES	16.01.2013	YES	YES	Calibration date has expired
			FLIR	Identifinder	910383-151	25.09.2012	YES	18.01.2013	YES	YES	Calibration date has expired
			FLIR	Identifinder	903555-279	21.11.2012	YES	04.04.2013	YES	YES	Calibration date has expired

gn

5	23	Nectar Inspection Services LLC, UAE	RAD/COMM	Mspec	200092	25.06.2014	Not given	15.06.2013	YES	YES	Supporting document of calibration not given
			RAD/COMM	-do-	200085	21.05.2015	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			RAD/COMM	-do-	200086	22.05.2015	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			RAD/COMM	-do-	200099	21.05.2015	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			RAD/COMM	-do-	200103	21.05.2015	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			lxc Radiation GMBH	ironMan High sensitive radioactive material finder & Dose rate Meter (Gamma Detect Systems for Scrap & Rcyl industries	901120-16	03.06.2013	Not given	15.07.2014	YES	YES	Supporting document of calibration not given
			Sebastopol CA-95472	Medcom Radalert 100X Nuclear radiation Monitor to detects Alpha, Beta, Gamma & X-radiation	X00779	May-15	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			Sebastopol CA-95472	-do-	X00573	May-15	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			Sebastopol CA-95472	-do-	X00717	Apr-15	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			Sebastopol CA-95472	-do-	73388	May-15	Not given	15.12.2012	YES	YES	Supporting document of calibration not given
			Sebastopol CA-95472	-do-	X00618	Apr-15	Not given	15.07.2014	YES	YES	Supporting document of calibration not given
			436, Farm Rd. Summertown P. O. Box 39, TN-38483 U.S.	-do-	447442	Feb-15	Not given	13.06.2012	YES	YES	Supporting document of calibration not given
			436, Farm Rd. Summertown P. O. Box 39, TN-38483 U.S.	-do-	447443	Jan-15	Not given	13.06.2012	YES	YES	Supporting document of calibration not given
			436, Farm Rd. Summertown P. O. Box 39, TN-38483 U.S.	-do-	447444	Jan-15	Not given	13.06.2012	YES	YES	Supporting document of calibration not given
			436, Farm Rd. Summertown P. O. Box 39, TN-38483 U.S.	-do-	28216	Apr-15	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			436, Farm Rd. Summertown P. O. Box 39, TN-38483 U.S.	-do-	28214	May-15	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
			436, Farm Rd. Summertown P. O. Box 39, TN-38483 U.S.	-do-	28215	May-15	Not given	28.05.2015	YES	YES	Supporting document of calibration not given
6	37	Supreme International FZC, UAE									
			Polimaster	PM1405	111552	23.03.2015	Yes	09.06.2015	YES	YES	OK
			Radcomm Systems	MSpec	200014	08.10.2014	Yes	05.06.2015	YES	YES	OK

gm

[illegible]

9	53	Global Marine Inspection,Unit, New Delhi	Radcomm	RHandy	100408	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100409	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100410	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100411	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100412	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100413	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100414	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100415	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100416	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	100417	08.06.2015	Not given	08.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	Mspec	200115	05.06.2015	yes	08.06.2015	YES	YES	OK
			Radcomm	Mspec	200114	05.06.2015	yes	08.06.2015	YES	YES	OK
			Radcomm	Mspec	200113	05.06.2015	yes	08.06.2015	YES	YES	OK
			Radcomm	Mspec	200190	05.06.2015	yes	08.06.2015	YES	YES	OK
			Radcomm	Mspec	200191	05.06.2015	yes	08.06.2015	YES	YES	OK
			Radcomm	Mspec	200192	05.06.2015	yes	08.06.2015	YES	YES	OK
			Radcomm	Mspec	200193	05.06.2015	yes	08.06.2015	YES	YES	OK
10	55	Olivine Commercial PTE Ltd, Singapore	Mirion Technologies (rados) Oy	RDS-30	312065	10.03.2015	YES	03.02.2014	YES	YES	OK
			Mirion Technologies (rados) Oy	RDS-30	312066	14.04.2015	YES	03.02.2014	YES	YES	OK
			RadComm	Rhandy	100385	13.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Rhandy	100386	13.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Rhandy	100425	13.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Rhandy	100382	8.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Rhandy	100383	8.10.2015	YES	26.10.2015	YES	YES	OK
			Laurus Systems	Syclone Portable Gamma-Ray Spectrometer	50049	14.04.2015	YES	19.03.2014	YES	YES	OK
			RadComm	Mspec	200200	08.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Mspec	200201	08.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Mspec	200202	08.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Mspec	200203	13.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Mspec	200204	13.10.2015	YES	26.10.2015	YES	YES	OK
			RadComm	Mspec	200205	13.10.2015	YES	26.10.2015	YES	YES	OK

			RadComm	Mspec	200206	13.10.2015	YES	26.10.2015	YES	YES	OK
11	56	Bureau Vertias india P Ltd, Mumbai	Thermo Fisher Scientific	RadEye PRD	30144	04.02.2014	Not given	03.04.2014	YES	YES	Supporting document of calibration not given
			Thermo Fisher Scientific	RIIDEYE M-G. part No. 4250860. PN 42508/60	10068	17.06.2015	yes	02.12.2013	YES	YES	Calibration date has expired
12	76	Ravi Energie Pvt Ltd, Baroda	Science Application International Corporation	GR-135	9091	NO	Not given	08.07.2013	YES	No	Supporting document of calibration & Date of calibration not given
			International Madcom Inc.	RadAlert 100	73449	Jul-14	Not given	11.12.2009	YES	YES	Supporting document of calibration not given
			International Madcom Inc.	RadAlert 100	73450	Jul-14	Not given	11.12.2009	YES	YES	Supporting document of calibration not given
			International Madcom Inc.	RadAlert 100	73451	Jul-14	Not given	11.12.2009	YES	YES	Supporting document of calibration not given
			International Madcom Inc.	RadAlert 100	S1668	Aug-14	Not given	28.08.2011	YES	YES	Supporting document of calibration not given
			International Madcom Inc.	RadAlert 100	S1669	Aug-14	Not given	28.08.2011	YES	YES	Supporting document of calibration not given
			International Madcom Inc.	RadAlert 100	S1670	Aug-14	Not given	28.08.2011	YES	YES	Supporting document of calibration not given
13	97	Transborder Safty Control Inspection Services LLC, USA	Radcomm	RHandy	CG/150017	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150018	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150019	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150020	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150021	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150022	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150023	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150024	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150025	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150026	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150027	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150028	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150029	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
			Radcomm	RHandy	CG/150030	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given

Radcomm	RHandy	CG/150031	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Radcomm	RHandy	CG/150032	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Radcomm	RHandy	CG/150033	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Radcomm	RHandy	CG/150034	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Radcomm	RHandy	CG/150035	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Radcomm	RHandy	CG/150036	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-10664	23.06.2015	Not given	23.07.2013	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-10665	23.06.2015	Not given	23.07.2013	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-10667	23.06.2015	Not given	23.07.2013	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-10668	23.06.2015	Not given	23.07.2013	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-10669	23.06.2015	Not given	23.07.2013	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11246	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11247	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11248	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11249	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11250	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11251	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11252	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11253	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11254	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11255	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11256	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11258	23.06.2015	Not given	23.06.2015	YES	YES	Supporting document of calibration not given
Shandong China	RAD 35	35-11259	23.06.2015	Not given	23.06.2015	YES	YES	SI.No & model name is not legible in photograph
Radcomm	MSpec	CGMS/600068	23.06.2015	YES	23.06.2015	YES	YES	OK
Radcomm	MSpec	CGMS/600069	23.06.2015	YES	23.06.2015	YES	YES	OK
Radcomm	MSpec	CGMS/600070	23.06.2015	YES	23.06.2015	YES	YES	OK
Radcomm	MSpec	CGMS/600071	23.06.2015	YES	23.06.2015	YES	YES	OK
Radcomm	MSpec	CGMS/600072	23.06.2015	YES	23.06.2015	YES	YES	OK
Radcomm	MSpec	CGMS/600073	23.06.2015	YES	23.06.2015	YES	YES	OK
Radcomm	MSpec	CGMS/600074	23.06.2015	YES	23.06.2015	YES	YES	OK
Radcomm	MSpec	CGMS/200060	23.06.2015	YES	25.05.2013	YES	YES	OK
Radcomm	MSpec	CGMS/200061	23.06.2015	YES	25.05.2013	YES	YES	OK

			Radcomm	MSpec	CGMS/200062	23.06.2015	YES	25.05.2013	YES	YES	OK
			Radcomm	MSpec	CGMS/200063	23.06.2015	YES	25.05.2013	YES	YES	OK
			Radcomm	MSpec	CGMS/200064	23.06.2015	YES	25.05.2013	YES	YES	OK
14	63	Tubby Impex P Ltd, New Delhi	SE International, Inc	Inspector Se	40288	15.07.2015	YES	15.05.2015	YES	YES	OK
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055287844040	15.05.2015	Not given*	15.05.2015	YES	YES	The authentic document showing the process of self-calibration is to be provided
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055287844088	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055287845061	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055287845016	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055287848079	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055287844033	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055287845023	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055288403079	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055288403055	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	5055287844071	15.05.2015	Not given*	15.05.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600015	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600022	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600039	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600046	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600053	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600060	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600077	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600084	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600091	17.06.2015	Not given*	17.06.2015	YES	YES	
			Slinya Group Holding Co Ltd., China	Rad-35 Radiometer Dosimeter	6936963600107	17.06.2015	Not given*	17.06.2015	YES	YES	
			Laurus Systems Inc.	MedSPec	200100	11.12.2013	YES	02.12.2013	YES	YES	Calibration date has expired
			Laurus Systems Inc.	MedSPec	200101	11.12.2013	YES	02.12.2013	YES	YES	Calibration date has expired
			Laurus Systems Inc.	MedSPec	200102	11.12.2013	YES	02.12.2013	YES	YES	Calibration date has expired
			Laurus Systems Inc.	MedSPec	200081	15.11.2013	YES	15.05.2015	YES	YES	OK
			Laurus Systems Inc.	MedSPec	200127	23.07.2015	YES	29.05.2015	YES	YES	OK
			Laurus Systems Inc.	MedSPec	200128	23.07.2015	YES	29.05.2015	YES	YES	OK
			Laurus Systems Inc.	MedSPec	200129	02.09.2015	YES	29.05.2015	YES	YES	OK
			Laurus Systems Inc.	MedSPec	200130	23.07.2015	YES	29.05.2015	YES	YES	OK

9m

			Laurus Systems Inc.	MedSPec	200131	23.07.2015	YES	29.05.2015	YES	YES	OK
			Laurus Systems Inc.	MedSPec	200132	03.09.2015	YES	29.05.2015	YES	YES	OK
			Laurus Systems Inc.	MedSPec	200133	03.09.2015	YES	29.05.2015	YES	YES	OK
			Laurus Systems Inc.	MedSPec	200134	03.09.2015	YES	29.05.2015	YES	YES	OK
			Laurus Systems Inc.	MedSPec	200015	16.01.2013	YES	15.05.2015	YES	YES	NOT OK
			Laurus Systems Inc.	MedSPec	200016	16.01.2013	YES	15.05.2015	YES	YES	NOT OK
			Laurus Systems Inc.	MedSPec	200017	15.01.2013	YES	15.05.2015	YES	YES	NOT OK
			Laurus Systems Inc.	MedSPec	200018	16.01.2013	YES	15.05.2015	YES	YES	NOT OK
			Laurus Systems Inc.	MedSPec	200019	16.01.2013	YES	15.05.2015	YES	YES	NOT OK
			Laurus Systems Inc.	MedSPec	200020	16.01.2013	YES	15.05.2015	YES	YES	NOT OK
			Laurus Systems Inc.	MedSPec	200021	16.01.2013	YES	15.05.2015	YES	YES	NOT OK
			Laurus Systems Inc.	MedSPec	200258	23.07.2015	YES	16.06.2015	YES	YES	OK
15	83	Asia Inspection Agency Co Ltd, Thailand	Rad/Comm Systems	Radiation Spectrometer	200126	23.07.2015	YES	29.05.2015	YES	YES	OK
			Rad/Comm Systems	Radiation Spectrometer	200075	30.09.2013	YES	16.09.2003	YES	YES	Calibration date has expired
			Rad/Comm Systems	Radiation Spectrometer	200076	23.09.2013	YES	16.09.2003	YES	YES	Calibration date has expired
			Rad/Comm Systems	Radiation Spectrometer	200077	30.09.2013	YES	16.09.2003	YES	YES	Calibration date has expired
			Rad/Comm Systems	Radiation Spectrometer	2000125	23.07.2015	YES	29.05.2015	YES	YES	OK
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 803	29.10.2013	NA*	29.10.2013	YES	YES	The authentic document showing the process of self-calibration is to be provided
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 810	29.10.2013	NA*	29.10.2013	YES	YES	
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 827	29.10.2013	NA*	29.10.2013	YES	YES	
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 834	29.10.2013	NA*	29.10.2013	YES	YES	
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 841	29.10.2013	NA*	29.10.2013	YES	YES	
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 858	29.10.2013	NA*	29.10.2013	YES	YES	
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 865	29.10.2013	NA*	29.10.2013	YES	YES	
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 872	29.10.2013	NA*	29.10.2013	YES	YES	
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 889	29.10.2013	NA*	29.10.2013	YES	YES	
			Slinya Group Holding	Rad-35 Radiometer Dosimeter	5055288406 896	29.10.2013	NA*	29.10.2013	YES	YES	
16	85	Geo Chem Middle East, UAE	Syclone	RadAlert	50031	24.10.2014	yes	19.09.2013	YES	YES	SI. No. not shown in photograph
			NDS 2000	NDS 2000	46276	07.01.2015	yes	20.01.2015	YES	YES	SI. No. not shown in photograph
			Radcomm	Rhandy	100426	08.10.2015	yes	13.10.2015	YES	YES	SI. No. not shown in photograph
			Radcomm	Rhandy	100381	08.10.2015	yes	13.10.2015	YES	YES	SI. No. not shown in photograph
			Radcomm	Rhandy	100382	08.10.2015	YES	13.10.2015	YES	YES	SI. No. not shown in photograph
			Radcomm	Rhandy	100383	08.10.2015	YES	13.10.2015	YES	YES	SI. No. not shown in photograph
			Radcomm	Mspec	200201	08.10.2015	YES	13.10.2015	YES	YES	SI. No. not shown in photograph
			Radcomm	Mspec	200202	08.10.2015	YES	13.10.2015	YES	YES	SI. No. not shown in photograph
			Radcomm	Mspec	200239	08.10.2015	YES	13.10.2015	YES	YES	SI. No. not shown in photograph
17	67	Geo-Chem Inspection SDN BHD, Malaysia	Larus Systems Inc	MedSpec	200091	28.07.2015	YES	17.4.2014	YES	YES	OK
			RadComm	Rhandy	100333	16.04.2014	YES	17.4.2014	YES	YES	OK
			RadoComm	Rhandy	100381	08.10.2015	YES	04.11.2015	YES	YES	OK
18	1	TSK Engineers P Ltd., Chennai	Gamma Scout	Gamma Scout with Alert	46402	30.10.2015	YES	30.10.2015	YES	YES	OK

9m

			Radcomm	Mspec	200207	01.12.2015	YES	25.11.2015	YES	YES	OK
--	--	--	---------	-------	--------	------------	-----	------------	-----	-----	----

gr

19	82	RMV Exim P Ltd., Delhi	SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32564	01.05.2015	YES	16.10.2014	YES	YES	The Committee decided to call the applicant with the machines in the next IMC meeting so that the machines can be checked by the Committee
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32570	01.05.2015	YES	16.10.2014	YES	YES	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32576	01.05.2015	YES	22.10.2014	YES	YES	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	23585	01.05.2015	YES	22.10.2014	YES	YES	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32643	01.05.2015	YES	28.10.2014	YES	YES	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32757	01.05.2015	YES	28.10.2014	YES	yes	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32810	01.05.2015	YES	5.11.2014	YES	yes	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32816	01.05.2015	YES	5.11.2014	YES	yes	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32835	01.05.2015	YES	25.11.2014	YES	yes	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32845	01.05.2015	YES	25.11.2014	YES	yes	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32867	01.05.2015	YES	28.11.2014	YES	yes	
			SE International, Inc	Inspector handheld Digital Radiation Alert Detector	32876	01.05.2015	YES	NO	NO	yes	
			Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54136	01.05.2015	YES	16.10.2014	YES	YES	
			Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54186	01.05.2015	YES	16.10.2014	YES	YES	
			Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54210	01.05.2015	YES	22.10.2014	YES	YES	
			Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54216	01.05.2015	YES	22.10.2014	YES	YES	

gm

		Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54326	01.05.2015	YES	28.10.2014	YES	YES	
		Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54332	01.05.2015	YES	28.10.2014	YES	YES	
		Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54337	01.05.2015	YES	5.11.2014	YES	YES	
		Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54339	01.05.2015	YES	5.11.2014	YES	YES	
		Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54446	01.05.2015	YES	26.11.2014	YES	YES	
		Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54568	01.05.2015	YES	26.11.2014	YES	YES	
		Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54671	01.05.2015	YES	28.11.014	YES	YES	
		Progressive Systems Company, Texas	Radscanner -500 Nuclear Radiation Monitor and Geiger Counter	RS54686	01.05.2015	YES	28.11.014	YES	YES	
		Laurus System	Mspec	230028	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230056	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230076	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230078	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230085	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230101	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230203	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230350	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230357	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230365	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230368	01.10.2015	YES	16.10.2014	YES	YES	
		Laurus System	Mspec	230385	01.10.2015	YES	16.10.2014	YES	YES	
20	98	Sunshine International Cargo Inspection Services Inc., Philippines								
		Radcomm System	R Handy	100500	22.09.2015	YES	15.9.2015	YES	YES	OK
		Radcomm System	R Handy	100501	22.09.2015	YES	15.9.2015	YES	YES	OK
		Radcomm System	R Handy	100502	22.09.2015	YES	15.9.2015	YES	YES	OK
		Radcomm System	R Handy	100503	22.09.2015	YES	15.9.2015	YES	YES	OK

gn

Radcomm System	Mspec	200123	21.09.2015	YES	10.9.2015	YES	YES	OK
Radcomm System	Mspec	200124	18.09.2015	YES	10.9.2015	YES	YES	OK
Radcomm System	Mspec	200198	18.09.2015	YES	10.9.2015	YES	YES	OK
Radcomm System	Mspec	200199	18.09.2015	YES	10.9.2015	YES	YES	OK

gr

